

**INDIAN INSTITUTE OF TECHNOLOGY GANDHINAGAR
SAFETY CENTRE**

Safety with Machines



Covered shoes must be worn at all times
Protect your feet



Safety goggles must be worn while working on any machine
Protect your eyes



Full face shield must be used while working on welding machine
Protect your face and eyes



long hair must be tied back



Don't put any part of body in moving machine
Prevent accident and injury



Know the operation and hazards during working on any machine



Clean up before leaving working place



**No Entry
Without Proper PPE**